

Project No: AFC 001 23 BCC

Project: Vandenberg AFB Supp. RI

Client: AFCEE Location: Site 2

Northing: 2104861.4

Borehole ID: HP-2

Date: 02/12/2001

(2MW-11)

Geologist: S. Zettle

Checked By: D. Smith, R.G.

Ground Surface Elevation: 480.26

Easting: 5799976.3

SUBSURFACE PROFILE					SAMPLE				
Depth	Symbol	Description	nscs	Elevation	Recovery %	Blow Counts (per 6")	PID (ppm)	Water Level	Remarks
5-		Clay with sand Dark yellowish brown, slightly moist, medium stiff, 75% clay, 15% sand, 10% silt; fill ?	CL	472					
15		Silty clay Grayish orange, moist, medium stiff, 75% clay, 20% silt, 5% sand; weathered mudstone?					0		
20-				458					
25		Clay with silt Pale yellowish brown, moist, medium stiff, 80% clay, 20% silt					0		
30-		unit becomes moderate yellowish brown, moist, very stiff, 80% clay, 20% silt; fractures present with iron staining							
10		@ 35' bgs		440	100	4\7\9	0		·
40-		Silty clay Dark yellowish brown, moist, very stiff,		435	100	5\6\12	0		
45-		70% clay, 30% silt Clay with silt			100	3/9/9	0		
50		Pale yellowish brown, moist, very stiff, low plasticity, 80% clay, 20% silt,			100	4\7\14	0		
55-		fractured, chert-like		423	100	3\5\9	0	¥	First encountered
60	***	unit displays iron and manganese staining @ 55' bgs			100	6/0/0	<u> </u>		groundwater @ 55.5' bgs
65		TOTAL DEPTH DRILLED = 57' BGS							
70-									
75-								L	

Drilled By: V & W Drilling

Drill Method: HSA

HydroGeoLogic, Inc. 4600 Northgate Blvd., Suite 207 Sacramento, CA 95834 (916) 614-8770 Fax: (916) 614-8775 Boring Diameter: 6" O.D.

Total Depth Drilled: 57' bgs

Drilling Equipment: Mobile B61

Sheet: 1 of 1

Sampling Equipment: Soil: 2" stainless steel lined CA modified split spoon sampler; Water: Hydropunch